

**PARKING BAY SPECIFICATIONS**

Concrete specifications for Sandhurst Club parking bay is as follows:

<b>Base material:</b>	32mpa grey cement with 7-10mm Hillview granite aggregate, 4% Abalox Inca Gold
<b>Size:</b>	6.5 metres by 2 metres
<b>Steel Dowel:</b>	200mm steel dowels into kerb and crossover every 600mm
<b>Concrete thickness:</b>	125mm
<b>Reinforcement:</b>	F72 steel
<b>Chairs:</b>	40mm

**Repair Works for Parking Bays:** Sandhurst Club Ltd. Repairs conducted by Sandhurst Club Estate Team are dependant of availability of contractors and weather conditions. Estate Management discretion applies.

Prior to pouring concrete please contact Grahame Rigby to arrange an inspection.

Inquiries can be made to Grahame Rigby, Estate Manager on office number 9702-7870, mobile 0400-336-188 or email [grigby@sandhurst.com](mailto:grigby@sandhurst.com)



*Sandhurst Club reserves the right to vary this information sheet at anytime as required without notice.*

Sandhurst Club Limited  
Proudly Managed By: PGA LINKS Management Pty Ltd ACN: 099 690 301  
75 Sandhurst Boulevard SANDHURST VIC 3977  
Phone: 03 8787-7011 Fax: 03 8787-7033  
Membership Services - Email: [golfclub@sandhurst.com](mailto:golfclub@sandhurst.com)

